

SPANGLE APPLICATION INSTRUCTIONS

Remove White Transfer Backing

Temp 288F-300F


Medium-Heavy Pressure

Press for 12-15 seconds

Rub transfer for 5-6 seconds.

Peel slowly and keep
tape close to garment.

If spangles lift, adjust transfer,
re-press and allow to cool longer
before peeling.



Thank you for your
business!

#BlingForEverybody

BlingForEverybody.com

info@blingforeverybody.com